




Cracked pinnacle stones



Cracked pinnacle stones



Cracked pinnacle summit stone with concrete fill to ferrous block.



Bird debris in upper tracery



Cracked hood moulding to the main west window



Loose cross pieces to west pinnacle above statue



Cracked inner moulding to main west window upper section below pointed arch.